



HARTMAN CONST. & EXCAV. INC.
1723 SOUTHVIEW DR.
INDIANAPOLIS IN. 46227
CELL # 317-339-3329

Number 1043

Date 8/3/2012

BILL TO

BEECH GROVE FIRE DEPARTMENT
330 EAST CHURCHMAN AVE.
BEECH GROVE IN. 46107

SHIP TO

BEECH GROVE FIRE DEPARTMENT
330 EAST CHURCHMAN AVE.
BEECH GROVE IN. 46107

10 DAYS

Description	Amount
CHURCHMAN STATION # 1	
REPAIR TOP OPENINGS ON THE TWO BACK OVERHEAD DOORS.	
RE-MOVE BOTH OVERHEAD DOORS.	
SHORE UP BOTH OPENERS.	
SHORE UP BLOCK ABOVE BEAM DURING REMOVAL OF BEAM.	
TOOTH OUT BRICK AND ONE OF BLOCK TO REMOVE BEAM.	
REMOVE AND INSTALL NEW I-BEAM.	
CLEAN BRICK AND RE-INSTALL BRICK AND ONE ROLL OF NEW BLOCK ON BEAM.	
INSTALL SPLIT FACE BLOCK ON TOP OF I-BEAM.(OUTSIDE ONLY)	
PAINT BLOCK INSIDE AND OUTSIDE 2 COATS.	
RE-INSTALL BOTH OVERHEAD DOORS AND OPENERS.	
TOTAL LABOR AND MATERIAL	\$13,125.00
INSTALL OVERHEAD DOOR WEATHER SEAL ON BOTH DOORS IN FRONT AND BACK.	
LABOR AND MATERIAL	\$510.00